## Department of Agrarian Development

## Preliminary Investigation Report For Minor Irrigation Schemes

Kikilige wewa 1.0 Name of the Scheme. 360920 N , 186536 E 2.0 Co-ordinate Anuradapura District 3.0 90, Penagama 4.0 G.N. Division 5.0 A. S. C. Area Kallanchiya 6.0 Access ( From the District office) Proceed along the kallanchiya kahatagasdigiliya road up to Penagama village turn right and proceed 300m to reach thetank bund 7.0 Tank Bund A) Length Varies 350.00 M E) Side Slope B) FSL 101.20 RL Normal F) Condition c) HFL 101.70 RL D) BTL 102.20 RL 8.0 Spill A) Type and Location : Natural crest ,L/B end 101.20 RL C) Crest Level Normal D) Condition B) Length 12M 9.0 Sluice Diameter Condition Type Location H/W Midle 225MM Normal Suwashakthi Detail of Farmer's Organization 10.0 L.Karunadasa , Penagama , Kedewa. Name of FO (Suraweera -0711442285) Information Supplied By: Present situation of the project 11.0 i The tank bund is in Normal condition ii Sluice & Spill are normal condition iii No propper canal system ......... No. of Farmer families benefited 12 Nos 12.0 20 Acres Irrigable extent 13.0

Signature

Date

T.M./Rathnamalala

Nechnical Officencering

Agrarian Development Department

Anuradhapura.