Department of Agrarian Development Preliminary Investigation Report For Minor Irrigation Schemes

: Konakumbuk wewa Name of the Scheme 1.0 : 185876E 362354N Co-ordinate 2.0 : Anuradhapura. District 3.0 : 91, Konakumbukwewa G.N. Division 4.0 : Kallanchiya A. S. C. Area 5.0 Proceed 2KM along the Kallanchiya Kahatagasdigiliya road Access 6.0 : upto Konakumbuk wewa to reach the tank bund. Tank Bund 7.0 1:2 E) Side Slope 585.00 M A) Length Good F) Condition 103.50 RL B) FSL 104.00 RL c) HFL 104.50 RL D) BTL Spill 8.0 103.50 RL C) Crest Leve A) Type and Location R/B end CO Good 30M D) Condition B) Length 9.0 Sluice Sill Level Condition Diameter Location Type Normal 100.30 225MM L/B **RCC Tower** 100.00 Normal 225MM R/B **RCC Tower** Detail of Farmer's Organization 10.0 Eksath FO, Konakumbuk wewa, Kendewa. Name of FO N.S.K. Jayawardana, (Secretary FO) Information Supplied By 077-8717212. Present situation of the Scheme 11.0 i The Tank bund is in good condition ii Sluices needs Routene Maintenance iii Need some repairs for the canal system. Farmers request Agri road along the R/B canal as they facing dificulty when

iv they caring Agricultural implements.

v

60 No.s No. of Farmer families benefited 12.0

98 Acres 13.0 Irrigable extent

G.Tennakoon

Name of the Engineering Assistant or Technical Officer



Date

