Department of Agrarian Development

Preliminary Investigation Report For Minor Irrigation Schemes

Messalawa wewa Name of the Scheme. 1.0 Co-ordinate 362082 N , 184659 E 2.0 Anuradapura 3.0 District 4.0 G.N. Division 90, Penagama 5.0 A. S. C. Area : Kallanchiya Access (From the District office) 6.0 Proceed along the kallanchiya kahatagasdigiliya road up to Aluthgama junction turn left and Proceed along the end of the Aluthgama tank bund reach the tank bund L/B end 7.0 Tank Bund A) Length 700.00 M E) Side Slope Varies B) FSL 102.10RL F) Condition Normal c) HFL 102.60 RL D) BTL 103.30 RL 8.0 Spill A) Type and Location : Spill cum course way C) Crest Level 102.10 RL B) Length 25 m D) Condition Normal 9.0 Sluice Location Type Diameter Condition L/B H/P/T 225MM Weak H/P/T R/B 225 MM Weak 10.0 Detail of Farmer's Organization Perakum S.Darmapala, Messalawa, Kedewa. Name of FO Information Supplied By: (Suraweera -0711442285) 11.0 Present situation of the project i The tank bund is in Normal condition

ii R/B sluice is no functioning,damage

iii Need Farm Turnout Structures for Both field canals

12.0 No. of Farmer families benefited : 22 Nos

13.0 Irrigable extent : 45 Acres

Agrarian Development Department Anuradhapura.

Signature

Date