

FO and tank information			Rehabilitation work				
No	Village/FO	Tanks	Tank bund	Sluice	Canal work	Other physical restoration	Partial desiltation
1	Mahakadiyawa	Mahakadiyawa	Repaired, earthwork and turfed	arrest RB sluice leak, fixing RCC pipes, minor repairs	R/B canal lining,	establish training bund and strip turfing, Earth cutting in tail canal (at spill)	Partial desiltation
2	Milagammana	Mailagammana	Earthwork in tank bund and gravelling along the tank bund	minor repairs of sluices	Canal lining of L/B and R/B	Pipe over crossing at RB canal	
		Mailagammana kuda wewa	Earthwork in tank bund and turfing		Construction of field canal earthwork and turfing		
3	Puliyankulama	Puliyankulama	Repaired, earthworks, gravelled and turfed	arrest mid sluice leak, fixing RCC pipes, minor repairs	L/B canal lining - concrete work	Construction of ramp and culvert to access the bund, repair to L/B canal after desilting process	Partial desiltation (Deepening), sealing the leak at the toe of the bund
4	Konakumbukwewa	Palugonameriyawa	Forming lower places of tank bund, earthwork and turfing	mid headwall sluice - cut open and put a RCC tower sluice	removing palmyrah tree strip, earthwork and turfind LB canal	Construction of RB side spill tail canal and training bund	
		Konakumbukwewa	Forming upstream abd downstream side slopes of the bund (1:1:2:), gravelling of the canal bud road	minor repairs of LB and RB sluices	Canal lining of RB sluice, L/B and RB farm turnout structures	Construct retaining wall at diversion place, establishing R/B canal bund road, constructing R/B canal overcrossing	Partial desiltation
5	Massalewa	Massalewa	Repaired, forming lower places and gravelling	Installing new LB sluices, minor repairs of RB sluice, Construction of lower level sluice	provide farm turnout at LB and RB canals	Improving spill tail canal, forming training bunds at RB spill canal, Earth reduction spill and widening of tail canal	Partial desiltation
	Massalewa	Aluthgama	Earthwork and gravelling	reconstruction of new headwall type mid sluice	Construction of farm turnouts	Widening of tail canal, construction of pipe overcrossing at LB canal, Spill canal construction and forming training bunds at LB canal	

FO and tank information			Rehabilitation work				
No	Village/FO	Tanks	Tank bund	Sluice	Canal work	Other physical restoration	Partial desiltation
6	Galkadawala	Galkadawala	Minor repairs and gravelling pof the tank bund	L/B - new lift rod, R/B - new sluice gate	RB canal concrete lining	bifurcation structure	
		Kohobagaswewa	Forming lower places of tank bunds	R/B - new lifting rod, concrete reinforce beam, R/B & L/B minor repairs	construction of L/B field canal and turfing		
		Wanniyankulam	Raise the bund, repaired, gravelled (full improvement)	Establish a new hume pipe tower sluice gate & fixing RCC pipes		Construction of RB side natural crest wall type new spill	
		Karuwalagaswewa			Construction of new RB canal and turfing of canal bund		
		Kayanwewa	Raising of tank bund	Minor repairs of hume pipe tower sluice	Costruction of earthen LB and RB field canals and turfing	Earth reduction at spill site	
7	Peenagama	Peenagama	Repaired, earthwork doen, gravelled, turfing	R/B & L/B sluice minor repairs	LB and RB canal lining		Partial desiltation
	Peenagama	Peenagama Kudawewa	Earthwork in the lower places of tank bunds	minor repairs for sluices, arrest water leak			
		Kikiligewewa	earthwork and turfing	minor repairs for sluices		Field canal earthwork and turfing	
8	Kuda Kadiyawa	Kuda Kadiyawa	Repaired, earthwork and turfed	Construction new sluice (and RCC pipe) at R/B, minor repairs in other sluices	Extension of mid sluice canal	Clear Overfall type spill at R/B end, construction of farm turouts	
		Kayangollewa	jungle clearing, earthwork, strip turfing			L/B spill tail canal and training bund construction, Construction of culvert at spill tal canal, forming eroded places of downstream road (peenagama to Puliyankulama, gravelling)	